

# Work Order (Bid Form)

Auditor: Scott Haislip (615) 274-2565 or (615) 424-2565

### **WORK ORDER INFORMATION**

Work Order Name: WO/10010MC1883/1

Work Order Type: Weatherization

**Audit Name: 10010MC1883** 

CLIEN	IT INFO	RMA	TION

Client Name: Address:

**Client ID:** 10010MC1883 MURFREESBORO, TN 37130

Alt. Client ID:

#### AGENCY INFORMATION

Agency: Mid-Cumberland Community Action Agency Agency Phone: (615) 742-1113

Fax:

Address: P.O.Box 310, 233 Legend Drive, Suite 103

Lebanon, TN 37088-0310 Email Address:

Company Name & License Number:	
Contractor's Signature	

#### **COMMENT**

SITE BUILT 1974 BRICK 1008 SQ FT MOISTURE PROBLEM IN ATTIC LEAD PAINT LIKELY

Client Name: Client ID: 10010MC1883 Alt. Client ID: DOE Weatherization Assistant Version 8.6.0 Page 1 of 12

## Measures

Measure 1 INSTA	ALL 2 SMOKE ALARMS	6		Componen	ts		1	nspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	2 SMOKE ALARMS	Each	2					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		DIED		Componen	<b>1</b> 0			nspected
Measure 2 INSTA	ALL 6 MIL VAPOR BAR FT; CONTRACTOR TO			Componen				nspected
Measure 2 INSTA	FT; CONTRACTOR TO	VERIFY		Estimated		Qty	Actual	
Measure 2 INSTA Comment 1008 SQ # Material / Labor			Qty 1	-		Qty		nspected Total
Measure 2 INSTA Comment 1008 SQ  # Material / Labor Health and Safety	FT; CONTRACTOR TO  Description / Comment	VERIFY <i>Units</i>	Qty	Estimated		Qty	Actual	
Measure 2 INSTA Comment 1008 SQ # Material / Labor	FT; CONTRACTOR TO  Description / Comment	VERIFY <i>Units</i>	Qty	Estimated		Qty	Actual	
Measure 2 INSTA Comment 1008 SQ # Material / Labor Health and Safety	FT; CONTRACTOR TO  Description / Comment	VERIFY <i>Units</i>	Qty	Estimated		Qty	Actual	
Measure 2 INSTA Comment 1008 SQ # Material / Labor Health and Safety	FT; CONTRACTOR TO  Description / Comment	VERIFY  Units  Each	<b>Qty</b> 1	Estimated			Actual	

	TALL POP OFF VALVE WATER HEATER	DRAIN LII	NE	Componen	ts		ı	Inspected
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	POP OFF VALVE DRAIN LINE	Each	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
	TEND BATHROOM EXHA SE TO EXTERIOR, APPR FT			Componen  Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	OTHER	Each	1					
Other Detail								
Other Detail								
			Measur	e Sub Total:		] :	Sub Total:	
Field Notes:								

Measure 5	SEAL PLUMBING PLUMBER KITCHEN SE			Componen	its		1	Inspected
Comment				Estimated	1		Actual	
# Material / Lab	oor Description / Con	nment Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			14	- Out Total		]	Sub Total:	
			weasur	e Sub Total:		<u>'</u>	Sub Total.	
Comment	UNDER BATHROOM COMMODE SUPPLY			Estimated	1		Actual	
# Material / Lab	oor Description / Con	nment Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								

Measure 7 WE	ATHER STRIP BACK DO	OOR		Componen	ts		ı	nspect
				Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	WEATHER STRIP	Each	1					
Other Detail	1					1		
						] []		
			Measur	e Sub Total:		] .	Sub Total:	
Field Notes:								
	D DOOR SWEEP TO BA	CK DOOR		Componen	ts		ı	nspecto
Measure 8 ADI	D DOOR SWEEP TO BA	CK DOOR		Componen	ts		1	nspecto
	D DOOR SWEEP TO BA	CK DOOR		<b>Componen</b> Estimated			I. Actual	nspect
Measure 8 ADI	D DOOR SWEEP TO BA	CK DOOR	Qty	•		Qty		nspect
Measure 8 ADI				Estimated		Qty	Actual	
Measure 8 ADI Comment  Material / Labor Other	Description / Comment	Units	Qty	Estimated		Qty	Actual	
Measure 8 ADI Comment  Material / Labor Other	Description / Comment	Units	Qty	Estimated		Qty	Actual	
Measure 8 ADI Comment : Material / Labor	Description / Comment	Units Each	<b>Qty</b> 1	Estimated			Actual	

	PAIR TILE ABOVE WATE TUB, 6-7 PIECES	ER FAUCE	Т	Componen	ts			Inspected
Comment				<b>-</b>	,			
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	OTHER	Each	1					
Other Detail						1		
			Measur	e Sub Total:		;	Sub Total:	
	AL CRACKS IN TRIM AB CHEN SINK WHERE LIG	_		Componen  Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	

_	REASE ATTIC INSULAT APPROXIMATELY 8" PF	_	-	Componen	its		1	Inspected
•	Q FT; CONTRACTOR TO							
	, , , , , , , , , , , , , , , , , , , ,			Estimated	ı		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	INSULATION	Each	1					
Other Detail								
						<u> </u>		
			Measur	e Sub Total:		,	Sub Total:	
Measure 12 INS	STALL ENERGY LID TO A	ATTIC PUI	LL	Componen	nts		1	Inspected
DO	STALL ENERGY LID TO A	ATTIC PUI	LL	•				Inspected
	WN STAIRS			Estimated		Qtv	Actual	Inspected
DO Comment		ATTIC PUI  Units  Each	<b>Qty</b> 1	•	ı	Qty		
DO Comment  # Material / Labor Other	WN STAIRS  Description / Comment	Units	Qty	Estimated	ı	Qty	Actual	
DO Comment # Material / Labor	WN STAIRS  Description / Comment	Units	Qty	Estimated	ı	Qty	Actual	
DO Comment  # Material / Labor Other	WN STAIRS  Description / Comment	Units	Qty	Estimated	ı	Qty	Actual	
DO Comment  # Material / Labor Other	WN STAIRS  Description / Comment	Units Each	<b>Qty</b> 1	Estimated	ı		Actual	

Measure 13 GL/	AZE WINDOW WN-3-S			Componen	ts		I	nspecte
<b>Comment</b> 36" X 4	0"; CONTRACTOR TO V	ERIFY						
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Windows	WINDOW GLAZING	Each	1					
Other Detail								
						]		
			Measur	e Sub Total:			Sub Total:	
Field Notes:	AZE WINDOW WN 4.6				40			nspocto
Measure 14 GL	<b>AZE WINDOW WN-4-S</b> 0"; CONTRACTOR TO V	ERIFY		Componen	ts		1.	nspecte
Measure 14 GL		ERIFY		<b>Componen</b> Estimated			I. Actual	nspecte
Measure 14 GL		ERIFY <i>Units</i>	Qty	-		Qty		nspecte
Measure 14 GL/Comment 36" X 4	0"; CONTRACTOR TO V			Estimated		Qty	Actual	
Measure 14 GLA Comment 36" X 4 # Material / Labor	0"; CONTRACTOR TO V  Description / Comment	Units	Qty	Estimated		Qty	Actual	
Measure 14 GL/ Comment 36" X 4  # Material / Labor Windows	0"; CONTRACTOR TO V  Description / Comment	Units	Qty	Estimated		Qty	Actual	
Measure 14 GL/ Comment 36" X 4  # Material / Labor Windows	0"; CONTRACTOR TO V  Description / Comment	Units Each	<b>Qty</b> 1	Estimated			Actual	

Measure 15 GL	AZE WINDOW WN-6-E			Componen	ts		I	nspecte
Comment 28" X 4	1"; CONTRACTOR TO V	ERIFY						
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Windows	WINDOW GLAZING	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
Measure 16 GL	<b>AZE WINDOW WN-2-W</b> X 55.25"; CONTRACTOR	R TO VERI		Componen	ts		1.	nspecte
Measure 16 GL	_	R TO VERI		<b>Componen</b> Estimated			I. Actual	nspecte
Measure 16 GL	_	R TO VERI		•		Qty		nspecte 
Measure 16 GLA	X 55.25"; CONTRACTOR		FY	Estimated		Qty	Actual	
Measure 16 GLa Comment 35.75" # Material / Labor	X 55.25"; CONTRACTOR  Description / Comment	Units	FY  Qty	Estimated		Qty	Actual	
Measure 16 GLA Comment 35.75"  # Material / Labor Windows	X 55.25"; CONTRACTOR  Description / Comment	Units	FY  Qty	Estimated		Qty	Actual	
Measure 16 GLA Comment 35.75"  # Material / Labor Windows	X 55.25"; CONTRACTOR  Description / Comment	Units Each	FY  Qty  1	Estimated			Actual	

	Measure 18 Storr	m Windows			Componer		-E,WN- I-4-S,W	-	Inspected
C	<b>Comment</b> 36" X 40 36" X 40 36" X 40 28" X 41	п п					·		
					Estimated	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Storm Window	SqFt	37.97					
2	Labor	Storm Window	SqFt	37.97					
3	Other	Storm Window	Each Window	4					
C	Other Detail						1		
L									
				Measure	e Sub Total:			Sub Total:	
	Measure 19 MAS	TIC SEAL REGISTERS	& RETUF	RN	Componer Estimated			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Heating Equipmen	MASTIC SEAL	Each	1					
C	Other Detail								
				Measure	e Sub Total:			Sub Total:	
	Field Notes:								

	ΓALL AIR FILTER & LE <i>l</i> ⁄IEOWNER	AVE 5 FOR	₹	Componen	ts		ı	nspecte
<b>Comment</b> 20" X 25	5"							
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipmen	AIR FILTERS	Each	1					
Other Detail								
			Measur	e Sub Total:		] ;	Sub Total:	
	V TANK INSULATION			Componen				nspected
Comment		Units	Qfv	Estimated	<u> </u>	Oftv	Actual	
Comment	V TANK INSULATION  Description / Comment  DHW TANK INSULATION	<i>Units</i> Each	<b>Qty</b> 1	-		Qty		nspected
Comment # Material / Labor	Description / Comment DHW TANK			Estimated	<u> </u>	Qty	Actual	
# Material / Labor Insulation	Description / Comment DHW TANK			Estimated	<u> </u>	Qty	Actual	
# Material / Labor Insulation	Description / Comment DHW TANK			Estimated	<u> </u>	Qty	Actual	
# Material / Labor Insulation	Description / Comment DHW TANK	Each	1	Estimated	<u> </u>		Actual	

Measure 22 DWH Pipe Insulation			Components					Inspected
Comment								
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	<b>Unit Cost</b>	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail						] [		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	STALL 3/4" PLYWOOD AWLSPACE DOOR W/HI	NGES &		Componen	ts		1	Inspected
CR HA		Т						Inspected
CR HA Comment 33" X 3	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO	<b>T</b> VERIFY		Estimated	<u> </u>		Actual	
CR HA Comment 33" X : # Material / Labor	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO Description / Comment	T VERIFY <i>Units</i>	Qty			Qty		Inspected
CR HA Comment 33" X 3	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO	<b>T</b> VERIFY		Estimated	<u> </u>	Qty	Actual	
CR HA Comment 33" X : # Material / Labor	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO Description / Comment	T VERIFY <i>Units</i>	Qty	Estimated	<u> </u>	Qty	Actual	
CR HA Comment 33" X 3 # Material / Labor Other	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO Description / Comment	T VERIFY <i>Units</i>	Qty	Estimated	<u> </u>	Qty	Actual	
CR HA Comment 33" X 3 # Material / Labor Other	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO Description / Comment	T VERIFY <i>Units</i>	Qty	Estimated	<u> </u>	Qty	Actual	
CR HA Comment 33" X 3 # Material / Labor Other	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO Description / Comment	VERIFY  Units Each	Qty 1	Estimated	<u> </u>		Actual	
CR HA Comment 33" X 3 # Material / Labor Other	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO Description / Comment	VERIFY  Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
CR HA Comment 33" X 3  # Material / Labor Other Other Detail	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO Description / Comment	VERIFY  Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
CR HA Comment 33" X 3  # Material / Labor Other Other Detail	AWLSPACE DOOR W/HI SP & 2 COATS OF PAINT 33.5"; CONTRACTOR TO Description / Comment	VERIFY  Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	